

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Problem Image Mailbox.**

Stephen B. Memory et al  
SUCTION LINE HEAT EXCHANGER FOR CO<sub>2</sub> COOLING SYSTEM  
Docket No. 00655P1222US




FIG. 1

Stephen B. Memory et al  
SUCTION LINE HEAT EXCHANGER FOR CO<sub>2</sub> COOLING SYSTEM  
Docket No. 00655P1222US




FIG. 2




FIG. 3






FIG. 4

Stephen B. Memory et al  
SUCTION LINE HEAT EXCHANGER FOR CO<sub>2</sub> COOLING SYSTEM  
Docket No. 00655P1222US



Stephen B. Memory et al  
SUCTION LINE HEAT EXCHANGER FOR CO<sub>2</sub> COOLING SYSTEM  
Docket No. 00655P1222US




FIG. 7